

What's New

Axel 7 Software

Axel Systems Ltd

The screenshot displays the Axel 7 software interface. The main window shows a 3D model of a part with a probe measuring a circular feature. The interface includes a menu bar (CAD Model, Alignment, Measure, Calculate, Results, CNC Program, CNC Feature, View, Setup, Desktop, Help), a toolbar with various measurement and modeling tools, and a 3D view area. A feature tree on the right lists features like Plane_1, Line_1, Line_2, Circle_1, Circle_2, Plane_2, and Circle_3. A data table at the bottom left shows measured values for Circle_2. A measurement display at the bottom right shows the coordinates X: 35.978, Y: 85.422, and Z: 1.901.

Circle_2	DP: 4/4	Rel. toleran:	Circle_2 / In:				
		Pts: Pnt0(FAC_37_5, 0, 0)	Pos: Plane_2				
Measured	Normal	Deviation	Up / Tol				
Dia	12.5503	12.5400	-0.005	0.0000	-0.0000	out	0.0000
X	30.0937	30.0937	0.0000	0.1000	-0.1000	in	0.0000
Y	79.7991	79.4794	-0.0043	0.0250	-0.0250	out	0.0000
Z	-10.2798	-10.2657	0.0069	0.0250	-0.0250	out	0.0000

X: 35.978
Y: 85.422
Z: 1.901

Contents

Introduction	1
Why upgrade to Axel 7	1
General	2
New user Ribbon interface	2
User Interface	2
Feature Properties dialog	3
New Results Window.....	3
All Results Tab with New points deviation graph	3
Large One Result Display	3
Large ‘During inspection results’ window	4
User Message Panel	4
Measure Window Toolbar.....	4
New Report.....	6
DMIS programming	6
Scan Features for articulated arms	7
New Alignment functions	8
3-2-1 Alignment.....	10
Customized user interface – colour schemes	11
CNC	12
Click & Measure.....	12
Collision avoidance.....	12
CAD Initial alignment.....	13
New CNC Parameters dialog.....	14
Graphical CNC feature edit	15
Automatic selection of Renishaw probe positions.....	16
Relative moves	16
Multiple Step program run	17
New Learn mode.....	17
CNC Parameters dialog.....	20
New CNC Feature program table 	21
Measure Windows Views.....	22
New PH10 probe window	23
Surface	24
Surface Block inspection.....	24
Surface Block CNC feature	24
CAD Pickup tools Options 	25
Pipe	26
New Pipe wizard.....	26

Deviation colour overlay	27
Pipe assembly inspection	27
Image	28
Video	28
Profile	29
New profile tab	29
Index	31

Introduction

Axel 7 is the new major release of our previous version. This document shows the main additions and changes over previous version. This is the major rewrite of our software. In addition to visible user interface changes and functionality, we have reorganised the inside of our software to cope with future requirements such as cloud and video inspection.

It offers fully integrated measuring environment that provides the solution to any metrology requirement. The innovative and unique user interface will guide through both manual and automatic inspection with ease.

It has been design to handle with the same ease inspection on CMM machines and measuring arms. Programming based on the CAD model cannot be any easier. You simply choose the CAD feature to measure and the rest is done for you.

Why upgrade to Axel 7

We recommend that the existing users read through this document. We personally believe that there are many reasons to upgrade to version 7. The first and obvious one is the *new CNC programming* operation. It cannot be any simpler. For most applications you will only need to choose the features you need to inspect and the program will be done for you. And for those special applications there is still our powerful programming engine.

In addition there are new features for CAD inspection and operating with *Articulated Measuring Arms*. New scanning options have been added.

The user interface has changed. It has been based on our already successful tabs and menus. Now with *Office 2007 feel and look* makes it a familiar platform for everyone.


And more importantly the software has been updated internally to allow for many new exciting features that will be coming out over in the new future.

General

New user Ribbon interface

Work smarter and faster with a uniform Ribbon interface. Our already successful interface of tabs and toolbars has been enhanced with Ribbon which accelerates the personal workflow and guarantees more efficiency in daily business.

The tabs on the Ribbon, display the commands that are the most relevant for each of the task areas in Axel. Long winded searching for needed commands is a thing of the past. The Axel button is a single entry point for settings and file management.








User Interface

Axel 7 User Interface has been designed for widescreen monitors

Feature Properties dialog


The New Feature Properties Panel displays inspected feature properties grouped together. Its data points are available at the glance as well as construction elements. Available tabs provide complete description of feature manual and cnc properties.

Feature property tab	Data points or feature element for constructions and alignment	CNC Feature program	Feature CNC program commands	Feature DMIS command
				


New Results Window

The Results Window displays results of the currently selected or measured feature.


All Results Tab with New points deviation graph



Large One Result Display



Large 'During inspection results' window



User Message Panel


Circle_2 DP: 0/4

Not enough data.

Arc ROI
Enter 3 points on the ARC, then drag to set the size

Measure Window Toolbar

The Measure Window Toolbar is docked by default on the left side of the Measure Window.




Measure Window Toolbar commands

Command	Description
Finish 	The Finish command is used to end various operations in Axel. This is a context sensitive button therefore its function will depend on the operation you are executing at the time. Typically you will use it to Finish current feature measurement or to exit from Go mode.
Cancel 	The Cancel command abandons the current feature measurement. If it was a new feature it will be removed from Feature List, if the feature was remeasured or continued, the original data points will be restored.
Go Mode 	The GO command starts or finishes the semiautomatic execution of Feature List. The Feature List is executed from the highlighted feature.
Repeat Mode 	The Repeat command is used to reselect currently measured type after feature. For example if the series of circles needs to be measured, selecting Circle feature with Repeat mode active, will automatically reselect the Circle feature after the previous one has finished.
Mouse selection modes 	Selects Measure Window operating mode.
Display Options 	Switches on and off display elements of the Measure Window.
3D 	The commands are used for choosing rendering mode for CAD model and measured features

CAD pickup Tool 	The commands are used for extracting CAD entities from CAD model.
Zoom Last 	Go to last zoom
Zoom Options A 	Zoom commands set A
Zoom Options B 	Zoom commands set B
Auto View Options 	Measure Window view options


New Report

New Axel report provides standard inspection results. It is shown as one of the Measure Window standard tabs.




DMIS programming

The DMIS tab displays the DMIS command for the currently selected feature.




Scan Features for articulated arms

Measuring Arm probe can operate in either single point or scanning mode. The selection is done with the button marked below.




When scanning mode is selected, the continuous train of data points may be collected for each geometric feature. As for the SET and SURFACE block features, points may be collected either at equal time or distance intervals or alongside predefined plane.

The dialog shown below appears when selecting SET or SURFACE feature. There are 3 possible scanning methods – 3D distance, Perpendicular plane section and Vertical Plane section.



The scan gallery allows easy access to specific scanning method.




New Alignment functions

The **Define Element command** is used for creating new Element coordinate system (Datum). It aligns axes of the part with the axes of the machine. The procedure is normally carried out at the start of the measurement, although there may be occasions where a new coordinate system may be required part way through the job.

Note: Only one Element system may be defined for the part. All other datums should be defined as Local coordinate systems and they are referenced to the Element datum.

The Define Element Dialog box .



The Define Element Dialog box

Use this box to define plane, line and origin for the alignment.

Option	Description
	Aligns a plane of the Element system. On pressing this button the Define Plane of <Element> window appears.
	Aligns an axis of the new Element system. On pressing this button the Define Axis of <Element> window appears.
	Aligns an origin of the new Element system. On pressing this button the Define Origin of <Element> window appears.



1 st feature	2 nd feature	3 rd feature	Plane calculation	Axis Calculation	Origin Calculation	Origin Projection
Plane	Line	Point		PROJ ln2-pl1		3D, Pl, Ax
Plane	Line	Line		PROJ ln2-pl1	INT ln2-ln3	
Plane	Plane	Point		INT pl1 – pl2		3D, Pl, Ax
Plane	Plane	Line		INT pl1–pl2	INT (pl1-pl2) - ln3	
Plane	Plane	Plane		INT pl1–pl2	INT pl1-pl2-pl3	
Plane	Point	Point		LINE pt2-pt3		
Line	Line	Point	Ln1 + Pt3	PROJ ln2-ln1		3D, ln1

Legend

PROJ ln2-pl1 – Projection of Line2 onto Plane 1


INT pl1-pl2 Intersection between Plane1 and Plane2

PLANE features	LINE features	POINT features
Plane, Round slot Rect. slot	Line Cylinder Cone Round slot Rect. Slot	Point Arc Circle Sphere Round Slot Rect. slot

Note: On selecting Element datum, program expects 3 data entry. It provides for quick alignment definition.


3-2-1 Alignment

3-2-1 Alignment will accept data points directly into set of features that define the alignment. The 3-2-1 gallery shows all available alignment options.



Customized user interface – colour schemes

Axel 7 is organised around familiar Office 2007 interface. In addition various colour schemes are available. The user interface is supplied with predefined desktop arrangements for manual, automatic, surface and pipe inspection.



CNC

AXEL 7 comes with extremely easy to use and flexible programming for CNC machines. It is virtually click and measure operation. At the same it maintains the powerful programming facility for those special applications that come along every now and then.

Click & Measure

Axel software strikes perfect balance between power and ease of use, Majority of applications can be handled with a simple Click and Measure functionality whereas for those special tough jobs there is a Visual Program Editor.

When creating a program using CAD, the feature CNC program is created immediately after the feature is extracted from the CAD. Also the approach sequence of moves is created taking the probe between the last measured feature and the newly created one avoiding crashes.


Also probe is automatically selected for the probe.

See the manual for detailed description of action taken when creating a feature CNC program.

Collision avoidance

When creating a program using CAD, Axel will automatically try to avoid collision when moving in between measured features.


Also when instructing to move to the selected feature, program will always check for possible collision and will alert the user about crash possibility.




CAD Initial alignment

The purpose of the initial alignment is to place the CAD model within the CMM machine model working range. The positioning of the part is important when using indexable probes such as MIH, PH10.


1. Import CAD part
2. It is recommended to switch off machine view now as it might obstruct the CAD.




3. From the CAD Model Tab, select CAD Initial Alignment



4. The Initial CAD alignment dialog box opens.




5. Probe the bottom plane. The part will rest on this plane on the machine base.
6. Using arrows in the Initial CAD alignment dialog adjust parts direction and height. It is important to align the same way as on the machine in order for PH9/10 direction to agree with the model.



New CNC Parameters dialog


All CNC parameters and setup have been placed together under 4 tabs within CNC parameter dialog.


Manual/CNC program options	Learn program tab – switching between Learn 7 and the original one	CNC RUN options	CNC program default parameters
----------------------------	--	-----------------	--------------------------------




Graphical CNC feature edit

To change the position of Plane data point (example)


1. The measured plane is not of regular rectangular shape. Please note that the 3rd probing point falls outside the plane. In order to move this point inside the plane, follow the steps below.
2. Press Edit  button to enter edit mode. The plane program is highlighted in Measure Window.




3. From Edit mode gallery choose Plane Parallel button. This option is for moving the data point position in the plane parallel to the measured plane.




4. Select Single in the Drag Element menu.




5. Position the mouse over the first data point on the left of the arc. The cursor changes.



6. Click and hold the left button and move mouse the data point is position on the plane.



7. To accept the new data point position click the right mouse button while holding left. Releasing left button doesn't not make any changes.



8. Make sure program is in Off-line mode and press Test  button to run Plane program. This time plane is measured at 4 points as expected.
9. Click Accept  button to save the newly changed sequence, to return to original click Undo.


Automatic selection of Renishaw probe positions

The position of PH10 is automatically selected during off line programming. User may select the current PH10 position or program may choose the optimal probe position for inspected feature.




Relative moves

Current feature program may be now easily referenced to any other feature.




Multiple Step program run

There is a gallery of Single move options. It will help in debugging and testing written programs.




Also program can be easily started from any feature or single selected feature can be executed. Of course there is still our normal option of setting a program breakpoint and setting program start point in the Visual Programming Window.



New Learn mode

There are times where program is written without CAD model. We have updated the Learn mode to fall within our standard program structure. Our new Learn mode is created in same way as you would create the program using CAD model. As a result once Learn program is created, each feature may be easily modified and feature program changed between Generated and Learn options.

We are confident you will find the new Learn program at great advantage and ease.




Create Learn Program - example

1. To create a CNC program in Learn mode, select Learn from the CNC Program Tab.




2. The Mode=Features in status bar will flash green,



the Measure Tab opens and Message is shown in the Results window.

Global learn mode.
Collect Approach moves for a new Feature


3. Program Manager is ready for collecting Learn moves



- Moves for each feature consist of approach moves, feature measurement moves and exit move. The approach moves are the moves from the previous feature exit point to current feature entry point. The entry point should be such that there is a clear and unobstructed path from it to the first feature data point.


Approach moves

- Press Space bar or Learn Button on the machine joystick to record machine position. Repeat entering moves to avoid any obstruction on the way until you get close to the feature you need to measure.
- Approach moves are recorded and shown in red in the program manager




Feature inspection


- From Measure Tab, choose Circle. Please make sure that there is a clear path between the last position of the approach and the first intended data point on the circle.



- Measure manually 4 points on the circle. If the default number of circle data points is set to 4, the feature measurements will terminate automatically after the 4th data point.



- After the last 4th point is entered, the circle is calculated and all the approach moves and feature inspection moves are presented as a single box in the Program Editor.




Exit Point

- Now the program waits for the Exit move to be recorded. The Exit point is normally entered at safe and convenient stand-off position. The Exit point entry completes feature program.
- Repeats steps 4 – 8 to measure more feature.
- Depress the Learn in the CNC Program Tab to finish the Learn sequence.


CNC Parameters dialog

Each feature CNC program is defined in the Feature CNC Program tab. The program is created based on its standard nominal or measured values with default parameters.



New CNC Feature program table


The CNC Feature program table displays the move commands that measure the feature. The probing, non-probing and probe change commands are shown.



Measure Windows Views

Each time new feature is defined from CAD, the current at the time view is also saved. When running CNC program, the view is recalled.

Views may be defined at any time.




New PH10 probe window

The Probe selection window has been redesigned. Each probe comes with its own predefined set of functions. There is also direct access to the probe calibration.



Probe Selection window with Select Styli Picture Box



Probe Selection window with Select Probing Directions Picture Box.


Surface

Touch Probe tip must be calibrated before any measurement can take place. Multiposition probes (star probes, MIH and PH9) must have each tip position calibrated. Program calculates tip diameter and its relative position from the reference one. Each probe has a reference tip marked in red on the list. All the other positions are referenced to it.


When calibrating or measuring a part you must first select the measuring probe and also its measuring position (tip) in case of multi position probes.

Surface Block inspection

The new Surface feature can be found in the Surface features section of the Measure ribbon.




The feature is used for grouping individual surface points under a single feature. It is also used for scanning with the scanning probe mounted on the machine or on measuring arm.



Surface Block CNC feature

The surface feature CNC feature program is created automatically. The Surface feature can be scan along a single line or around the selected area in grid fashion.



CAD Pickup tools Options

The commands are used for extracting features from CAD model. The range of available commands allows extracting just about any geometric or surface feature from CAD files.

CAD Single Data Point

 **Mouse Surface Point**
mouse RB surface click

 **Edge Points Mode**
edge point RB selection

CAD Entity Mode

 **Edge Mode**
convert edge to feature

 **Surface Mode**
convert surface to feature


Feature As Data Point

 **Feature Result**
Use feature results as data


 **Feature Data Points**
Copy feature data points to the new feature

Pipe

New Pipe wizard



Deviation colour overlay



Pipe assembly inspection

ASSEMBLY - LEG 1 definition

Number of straights: 1

Default no of points per straight: 6

Tube shape: Round

Tube diameter: 0.00 mm

Bend radius: 0.00 mm

Tolerance band: 0.00 mm

Enable Brackets:

END POINTS

Start point type: single point projected

Start point correction: Into pipe

End point type: single point projected

End point correction: Into pipe

End point runout (DN)

Buttons: Generate pipe, OK, Cancel, Help



Image

Video

New module to handle camera inspection. Fully integrated with Axel, can also be supplied as stand alone.


Key features

- ❑ **Add-on module for Axel Software** – Vision software is available as an stand alone package for Video CMM machines or as an addition for our Axel Metrology Suite for CMM machine where Touch Probe and Image Probe are both installed.
- ❑ **Geometric Features** – full range of geometric inspection features measured with wide range of image tools.
- ❑ **Auto Feature** – one click operation to measure the range of features.
- ❑ **Adaptive Edge Detection Techniques** – Extensive set of edge detection tools is available. Automatic edge detection within defined ROI, auto edge points. Edge detection comes with tools and setups to deal with variety of surface finishes and lighting conditions.
- ❑ **AutoFocus** – Build in autofocus is offered for manual and automatic video systems to increase inspection accuracy.
- ❑ **Dual Screen Operation** – Video inspection can be configured for dual screen operation
- ❑ **Reverse Engineering** – features to reverse engineer parts with export to CAD packages.
- ❑ **Go-Mode** – Automatic Feature List program creation for repetitive running of inspection routines with user defined messages.
- ❑ Go mode auto view play to enhance feature inspection
- ❑ DDE / File / Serial Data export to SPC & Excel
- ❑ Export results to **MS Excel and HTML** with multiple templates
- ❑ User configurable, fully featured text & Graphical Report Generator



Profile

New profile tab



Coloured deviations

Best fit

Best fit Calculation

Enable best fit calculation Animation

X Y Rotation

0.0354 0.0062 -0.0312 [deg]

Initial Transformation

Use Initial Transformation

X: 0.000 Y: 0.000 R: 0.000

OK Cancel Help

Unknown profile scanning – camera and touch probe

Index

3

3-2-1 Alignment 10

A

All Results Tab with New points deviation graph 3
Automatic selection of Renishaw probe positions 16

C

CAD Initial alignment 13
CAD Pickup tools Options 25
Click & Measure 12
CNC 12
CNC Parameters dialog 20
Collision avoidance 12
Customized user interface - colour schemes 11

D

Deviation colour overlay 27
DMIS programming 6

F

Feature Properties dialog 3

G

General 2
Graphical CNC feature edit 15

I

Image 28
Introduction 1

L

Large 'During inspection results' window 4
Large One Result Display 3

M

Measure Window Toolbar 4
Measure Windows Views 22
Multiple Step program run 17

N

New Alignment functions 8
New CNC Feature program table 21
New CNC Parameters dialog 14
New Learn mode 17
New PH10 probe window 23
New Pipe wizard 26
New profile tab 29
New Report 6
New Results Window 3
New user Ribbon interface 2

P

Pipe 26
Pipe assembly inspection 27
Profile 29

R

Relative moves 16

S

Scan Features for articulated arms 7
Surface 24
Surface Block CNC feature 24
Surface Block inspection 24

U

User Interface 2
User Message Panel 4

V

Video 28

W

Why upgrade to Axel 7 1